

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

Building Name	Material Description	Location*
<b>Betsy Barbour Residence Hall</b>	Fire Doors (Assumed Positive)	Throughout Building
	Floor Tile	111, 223, 323
	HVAC Fabric	B15, B23, B23D, 4C01
	Pipe Insulation (Straights)	Basement, First and Second Floors
	Pipe Insulation (Fittings)	Basement, First and Second Floors
	Window Caulking	B09J

\*Room numbers listed are as identified at the time of the survey