

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Cooley Memorial Building	Canvas Duct Insulation	BC95
	Ceiling Tile Gluepod	GC91, GC93, 1S91, 1922, 1943, 1947, 1947A, 2911A, 2911B, 2915A, 2915B, 2919A, 2919B, 2923A, 2923B
	Chalkboard (Presumed)	2918
	Cove Base Mastic	G904, GS97, 1S97, 1916A, 1928A, 1940, 1946, 1946A, 1946B, 1956, 1958, 1959, 2S97, 2919, 2919A, 2919B, 2934, 2959, 2964, 2970, 2970A
	Floor Tile	Throughout Building
	Floor Tile Mastic	2964, 2970, 2970A
	Fire Door	Throughout Building
	Fume Hood Liner (Presumed)	1963
	HVAC Fabric	G933, 2950J
	Light Heat Shield	GC91, Tunnel to PML
	Pipe Insulation (Fittings)	B922A, GC97, G906, G906A, G932E, G935, G963A, 2918
	Transite Paneling	1922, Tunnel to PML

*Room numbers listed are as identified at the time of the survey