

The table below describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in inaccessible locations, such as above fixed ceilings and inside wall cavities. Asbestos-containing material (ACM) means any material containing more than 1% asbestos. If you have any questions or concerns regarding asbestos containing materials please contact the Environment Health & Safety (EHS) office at 734-647-1143 or you may refer to the [Asbestos information page](http://www.ehs.umich.edu) found on the EHS website ([www.ehs.umich.edu](http://www.ehs.umich.edu)).

<b>Building Name</b>	<b>Material Description</b>	<b>Location*</b>
<b>Dental School Building (Excludes the Kellogg Institute)</b>	Black Tar Roof Drain	6223
	Door Panel Insulation	G311A, G311B, G327E, G327J, 1038E, 1040J, 1203J, 1215E, 1325, 1327J, 1327D, 2V23, 2219J, 2327E, 2327J, 3327E, 3327J, 3328
	Duct Caulk	G066P, 2C33, 2325, 2381, 2310, 2310A, 2310J, 2310K, 2310L, 3310, 3310B, 3310E, 3310F, 3310G, 3310I, 3310J, 3310K, 3310L, 3310M, 3310O, 3310P, 8205M
	Epoxy Floor Dam Mastic	4327M
	Fire Door & Frame (Presumed)	Throughout Building
	Flooring Material (Roofing)	B398, 3V23
	Floor Tile & Mastic	Throughout Building
	Fume Hood Liner	Various Locations Throughout
	Intake Caulk	Building Exterior
	Lab Drying Rack	5204, 5216, 5222
	Metal Duct Mud Insulation	Various Locations Throughout
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Sink Undercoating	Various Locations Throughout
	Transite Panel	4327M, Building Exterior

\*Room numbers listed are as identified at the time of the survey