

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Facility Services Building A	Ceiling Tile Gluepods (Presumed)	1306D
	Fire Door (Presumed)	1C03, 1050C, 1144, 1306H, 1432C, 1450M, 1800A, 1802E, 1804, 1804A
	Floor Tile	1C02, 1100B, 1100C, 1014, 1014A, 1014E, 1015, 1015A, 1015B, 1029, 1031, 1036, 1136B, 1257, 1027M, 1257A, 1268, 1400A, 1400B, 1400C, 1400D, 1400E, 1400G, 1400H, 1400I
	Overhead Door Caulk	Building Exterior
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Transite Paneling	1254, 1306, 1308A, 1308B, 1310, 1511, 1511B, 1005-1025, Telephone Attic
	Window Caulk	1269T, Building Exterior

*Room numbers listed are as identified at the time of the survey