

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Facility Services Building C	Fire Door (Presumed)	Throughout Building
	Floor Tile	1022B, 1037, 1037C, 1037D, 1038A
	Louver Caulk	Building Exterior
	Pipe Insulation (Straights) (Presumed)	1004, 1022
	Pipe Insulation (Fittings)	1C71, 1002, 1004, 1004A, 1022, 1037B, 1037C, 1038, 1040, 1072, 1080,
	Steam Line Heat Protection Board	1022, 1022C6, 1038, 1040, 1044, 1052, 1072, 1M72
	Transite Ceiling Panel	1184, 1186
	Transite Door Panel	1004
	Transite Fascia	Building Exterior
	Transite Paneling	1004, 1022C6
	Transite Drain Pipe	1002, Building Exterior
	Window Putty	1004

*Room numbers listed are as identified at the time of the survey