

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Lay Automotive Lab	Ceiling Tile Gluepod	1C06, 2C01, 2C03, 2V06, 2007, 2011, 2015, 2019, 2023, 2027, 2031, 2033, 2039, 2043, 2045, 2052A, 2064T
	Duct Insulation Wrap	2070
	Duct Seam Tape	2070
	Fire Door (Presumed)	Throughout Building
	Floor Tile	Throughout Second Floor
	Fume Hood Cabinet Liner	2070A
	Fume Hood Liner (Presumed)	2070A
	HVAC Wrap	2070
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Transite Panel Cover	2070, 2070D, 2070E

*Room numbers listed are as identified at the time of the survey