

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

<b>Building Name</b>	<b>Material Description</b>	<b>Location*</b>
<b>News &amp; Information Services</b>	12" X 12" Plasterboard	1C01, 1F01, 1L07, 100, 100B, 101, 102, 102A, 102C, 105, 108, 109T, 110, 111J, 2S01
	Ceiling Tile Gluepod	1C01, 1F01, 1L07, 100, 100B, 101, 102, 102A, 102C, 105, 108, 109T, 110, 111J, 2S01
	Door Frame Caulk	Building Exterior
	Duct Insulation	2
	Fire Door (Presumed)	BS01, 3, 1S01, 100B, 102, 2S01
	Floor Leveling Compound	1C01, 100B
	Floor Tile	3, 7, 8, 11, 12
	Pipe Insulation (Straights)	2, 3, 7, 8, 11, 12, 102, 211T, 212
	Pipe Insulation (Fittings)	2, 3, 7, 8, 11, 12, 102, 211T, 212
	Vent Caulk	Building Exterior
	Window Caulk	Building Exterior
	Window Panel Caulk	Building Exterior

\*Room numbers listed are as identified at the time of the survey