

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Oxford House – Vandenburg Hall	Backsplash Caulk	B115
	Carpet Mastic	Throughout Building
	Cove Base & Mastic	B1, B1A, B127E
	Door Caulk	B103, B114, B116
	Fire Door (Presumed)	Throughout Building
	Floor Tile	BS02, BS03, B103, B105E, B127E, B132J, B203E, B207, B229E, B232J, B301E, B307, B327E, B332J, 1S01, 1S02, 1S03, 1S04, 2C02, 2S01, 2S02, 2S03, 2S04, 3S01, 3S02, 3S03, 3S04
	Floor Tile Mastic	B103, B104, B118, 1C03, 1C04
	HVAC Fabric (Presumed)	B117J
	Pipe Insulation (Fittings)	Throughout Building
	Register Fabric Pipe Wrap	Throughout Building
	Sink Undercoating	B115, B235
	Window Caulk	B103, B114, B116, 2C01

*Room numbers listed are as identified at the time of the survey