

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
School of Nursing (400 North Ingalls)	Blackboard (Presumed)	1184, 1188, 1220, 1230, 1240, 1310, 1334, 1338, 2151, 3151, 3303, 4347
	Ceiling Tile Gluepod	G152, G160, 170B, 170C
	Ceiling Material	1240
	Door Caulk	Building Exterior
	Fire Door (Presumed)	Throughout Building
	Floor Tile	Throughout Building
	Floor Tile Mastic	GE03, 3F02
	Fume Hood Liner (Presumed)	G160, 2220, 2227
	Lab Table Tops (Presumed)	G152, G160, G163, 170B, 170C,
	Light Heat Shield	1S04, 228P, 3227
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Plaster Ceiling	2216
	Transite Panel	Throughout Building
	Vinyl Sheeting	G170, 1240, 2214, 2216, 2220, 2226

*Room numbers listed are as identified at the time of the survey