

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
South Quadrangle	Boiler Insulation	B100A, B100B, B100D
	Covebase	Throughout Building
	Ductwork Sealant	1C01, 111
	Electrical Wire Covering (Presumed)	3E04
	Elevator Door Caulk	3E04
	Fire Door (Presumed)	Throughout Building
	Floor Tile	Throughout Building
	Floor Tile Mastic	Throughout Building
	HVAC Fabric (Presumed)	B100, B100A, B100C, B100D, G118A, G138, G143A, G143B, G145, 114, 118, 9002, 9502, 10001M, 10501M
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Plaster Wall/Ceilings	Various Locations Throughout Building
	Tank Insulation	B100B, B100C
Window Caulk	1F05	

*Room numbers listed are as identified at the time of the survey