


After using radioactive material and prior to leaving the area, survey the work area and yourself for radioactive contamination.



Use the contamination swipe method when handling H-3.

After-hours emergency, contact  
the U-M Police Department  
(734) 763-1131 or dial 911

University of Michigan  
Environment, Health & Safety  
[www.ehs.umich.edu](http://www.ehs.umich.edu)    (734) 764-6200