

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Art and Architecture	Fire Doors (Assumed Positive)	Throughout Building
	Floor Tile / Sheeting	Throughout Building
	Floor Tile / Sheeting Mastic	2147, 2204, 2205, 2206, 206A, 2C11, 2C14, 2C16, 2C22
	Lab Table Top	1069, 1069A, 1069B, 1071, 1072, 2126
	Light Heat Shield	147T, 1009, 1010, 1011, 1012, 1013, 1014, 1015, 1016, 1017, 1018, 1019, 1020, 1021, 1022, 1023, 1024, 1025, 1027, 2110
	Sink Undercoating	1C05, 1067, 1069, 1075, 2C05, 2048, 2063, 2092, 2134, 3100
	Transite Work Space Divider	1069
	Window Caulk	Building Exterior

*Room numbers listed are as identified at the time of the survey