

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

| Building Name | Material Description | Location* |
|--|---------------------------------------|--|
| Biological Station / Residence Hall | Fire Doors (Presumed) | 103 |
| | Floor Tile and Mastic | 100, 101, 102, 104, 105, 106, 107, Linen Room |
| | HVAC Vibration Dampener (Presumed) | 103 |
| | Light Heat Shields | Throughout Building |
| | Pipe Insulation (Fittings) | 103, 104, H-1 |

*Room numbers listed are as identified at the time of the survey