

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Engineering Research Building I	Door Frame Caulk	Building Exterior
	Fire Doors (Presumed)	BC14, 1109A, 6108A, 7107, 7120, 7S13
	Floor Tile	Throughout Building
	Floor Tile Mastic	Throughout Building
	Fume Hood Liner (Presumed)	112, 113
	HVAC Fabric - Canvas	110, 7120
	Lab Drying Rack	111, 112
	Lab Table Top	106, 111, 112, 113, 4112
	Mudded Duct Insulation	BC12
	Pipe Insulation (Fittings)	Throughout Building
	Roof Tar	7107, 7118, 7120
	Sink Undercoating	111, 113A, 6112A
	Wall Base Caulk	Building Exterior

*Room numbers listed are as identified at the time of the survey