

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Environmental & Water Research Engineering	Black Flooring Material	300
	Black Window Caulk	Building Exterior
	Fire Door (Presumed)	Throughout Building
	Flooring Material (Black)	300
	Floor Tile	Throughout Building
	Floor Tile Mastic	Throughout Building
	Fume Hood Liner (Presumed)	6, 12, 18, 20, 26, 30, 36, 87,
	Lab Drying Rack	169, 206, 212, 221, 263, 273, 3,
	Oven Insulation (Presumed)	6, 7, 12, 13, 17, 19, 20, 34, 40,
	Tan Duct Adhesive	87, 169, 211, 212 220, 221,
	Window Caulk	255, 263, 273A, 275, 283
	87, 169, 206, 212, 263, 275	
	300	
	Building Exterior	

*Room numbers listed are as identified at the time of the survey