

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

Building Name	Material Description	Location*
<b>Hutchins Hall</b>	Ceiling Tile Gluepod	307
	Cove Base Mastic	116, 213, 218, 330B
	Fire Door (Presumed)	B1E, 300A
	HVAC Fabric	B1E
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Plaster Ceiling	Throughout Building
	Plaster Wall	Throughout Building
	Radiator Enclosure	Throughout Building
	Sink Undercoating	344

\*Room numbers listed are as identified at the time of the survey