

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

Building Name	Material Description	Location*
<b>Institute for Science and Technology South</b>	Drying Rack	M4912
	Exhaust Fan Caulk	Building Exterior
	Fire Door (Presumed)	MIC01, M4859, M4901S, M4917
	Floor Tile	M4852, M4853, M4855, M4856, M4857, M4859A, M4861, M4912, M4914
	Lab Table Top	M4916
	Wall Caulk	Building Exterior
	Window Caulk	Building Exterior

\*Room numbers listed are as identified at the time of the survey