

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

Building Name	Material Description	Location*
<b>Lorch Hall</b>	Ceiling Panel (Presumed)	140
	Cove Base & Mastic	173C
	Duct Adhesive	Throughout Building
	Fire Door (Presumed)	Throughout Building
	Fireproofing	B40
	Floor Tile & Mastic	171, 173, 173C, 451, 453A, 453B, 453C, 455A, 455B, 455C, 457A, 457B, 457C, 457D, 461A, 431B, 463A, 463B, 465A, 465B, 475S, 491, 499
	Floor Underlayment & Mastic	171, 173, 335, 335A, 337, 339, 341, 343, 373, 440, 440B, 440C, 440D, 450, 454, 458, 462, 466
	Pipe Insulation (Straights)	B40, B43, 241S, 335, 335A, 341S
	Pipe Insulation (Fittings)	B43, 335, 335A
	Radiator Side Panel	265
	Vinyl Sheet Mastic	400, 401, 402, 403, 406, 407, 408, 409, 411, 412, 413, 414, 417, 418, 419, 421, 432E, 434P, 441, 496
	Wall Joint Caulk	Building Exterior

\*Room numbers listed are as identified at the time of the survey