

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Martha Cook Residence Hall	Cork Ceiling	B25
	Duct Insulation	B05, B11, B12, B19, B26
	Fire Door (Presumed)	502M
	Floor Tile	BC01, BF01, BS05, B09, 020, 020A
	Metal Duct Wrap	BS05
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Radiator Backing Material	010A, 013, 013A, 017
	Round Light Fixture Heat Shield	Throughout Building
	Wall Covering	BC01, BF01, BS10, 1C07, 1C09, 1S10

*Room numbers listed are as identified at the time of the survey