

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Original Law Quad	Boiler Insulation	B011M
	Electrical Wire Insulation (Presumed)	Throughout Building
	HVAC Expansion Joint (Presumed)	B020W
	HVAC Duct Wrap	BC09, B012, B013, B017
	Fire Door (Presumed)	Throughout Building
	Floor Tile	BC02, BC03, B02, 130P
	Light Heat Shield	309
	Pipe Insulation (Straights)	Throughout Basement
	Pipe Insulation (Fittings)	Throughout Building

*Room numbers listed are as identified at the time of the survey