

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

Building Name	Material Description	Location*
<b>Oxford House – Goddard Hall</b>	Backsplash Caulk	A115
	Door Caulk	A103, A114, A116
	Floor Tile	BS01, BS02, 1C01, 1C02, 1C03, 1S01, 1S02, 1S03, 1S04, A103, A105E, A116, A116A, A121, A127E, A132J, 2C01, 2C03, 2S01, 2S02, 2S03, 2S04, A203E, A207, A229E, A232J, 3C01, 3C03, 3S01, 3S02, 3S03, 3S04, A301E, A307, A327E, A332J
	Fire Door (Presumed)	Throughout Building
	Floor Tile Mastic	1C01, 1C02, A103, A116, A116A, A121
	HVAC Fabric (Presumed)	A117J
	HVAC Tar	TV07
	Pipe Insulation (Straights)	TV01, TV03, TV06, TV07, TV08, A1, A2, A3, 1S02, 2S04, 3S02, 3S03, 3S04
	Pipe Insulation (Fittings)	Throughout Building
	Window Caulk	A103, A114, A116, 2C03, 3C03

\*Room numbers listed are as identified at the time of the survey