

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

Building Name	Material Description	Location*
<b>Ruthven Museum</b>	Ceiling Panel	4516
	Drying Rack	86, 90, 94, 1053, 1055, 1085, 1094, 2081, 2091, 3048, 3081, 3085, 3091, 4076, 4080, 4085, 4088
	Fireproofing	4033E, 4033T, Attic
	Fire Door (Presumed)	Throughout Building
	Floor Tile	Throughout Building
	Fume Hood Liner (Presumed)	1026, 1517, 2032, 2038, 3026, 3089, 4016, 4089
	Lab Bench Top	Throughout Building
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Transite Wall Panel	5035
	Vinyl Floor Sheet	BC11, BC15, BS05, BS06, BS5M, BS6M, 1C11, 1S06, 2C11, 2S06, 3C03, 3C05, 3C07, 3S06, 3052, 4C11, 4S06, Elevator E6

\*Room numbers listed are as identified at the time of the survey