

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
School of Music (Moore Building)	Boiler Breeching Pipe Coating	1008M
	Ceiling Tile Gluepod	Throughout Building
	Duct Insulation	100, 1009M
	Electrical Wire Insulation (Presumed)	4250
	Fire Door (Presumed)	Throughout Building
	Floor Tile	Throughout Building
	Foundation Tar Paper	Building Exterior
	Pegboard/Transite Panel	1320, 1340, 1V32
	Pipe Insulation (Fittings)	Throughout Building
	Transite Panel	13200, 1340A
	Univent Caulk	Building Exterior
	Vinyl Sheeting & Mastic	4S26, 4MS26
	Wall Caulking	Building Exterior
	Window Caulking	Throughout Building

*Room numbers listed are as identified at the time of the survey