

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

<b>Building Name</b>	<b>Material Description</b>	<b>Location*</b>
<b>Simpson Memorial Institute</b>	Black Duct Coating	205, 205A, 206, 209, 212, 300
	Black Wall Flashing	Building Exterior
	Duct Insulation	56A
	Fire Door (Presumed)	Throughout Building
	Floor Tile	50, 50A, 50B, 52, 53, 54, 55, 56B
	Lab Table Top	50, 50A, 51, 52, 53, 114, 114A, 206, 300, 301A, 308
	Light Heat Shield	2S01, 4S01
	Pipe Insulation (Straights)	BC01, 3, 50, 50A, 52, 54, 54A, 55A, 56, 56A, 56B, 102, 103, 109, 109A, 114, 201
	Pipe Insulation (Fittings)	Throughout Building
	Sink Undercoating	50, 53, 109, 114, 300
	Tank Insulation	401
	Transite Cabinet Liner	205
	Transite Fume Hood Liner (Presumed)	50A, 51, 205, 209, 212, 311
	Transite Wall Panel	50, 50A, 100, 102, 104
	Window Frame Caulk	Building Exterior

\*Room numbers listed are as identified at the time of the survey