

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Bursley Hall	Breeching Insulation	1307
	Ceiling Tile Gluepods	1C43, 2C01, 2C41, 4C61, 4C63,
	Ceramic Tile Backer Board	5C23, 5C61, 5C63, 6C21, 6C23 2C12
	Covebase and Mastic	Throughout Building
	Floor Tile	Throughout Building
	Floor Tile Mastic	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Plaster Ceiling	1C43, 2C01, 2C03, 2C41, 2C42,
	Textured Concrete Ceiling	2C43, 3C01, 3C03, 4C01 4C03, 4C23, 4C61, 4C63, 5C21, 5C23, 5C61, 5C63, 6C21, 6C23
	Throughout Building	

*Room numbers listed are as identified at the time of the survey