

FOOD ESTABLISHMENT INSPECTION REPORT

Based on an evaluation this day, the items marked below are violations of the Michigan Food Law. Violations cited in this report shall be corrected within the time frames specified below, but within a period not to exceed 10 calendar days for priority or priority foundation items (§8-405.11) or 90 days for core items (§8-406.11). Failure to comply with this notice may result in license suspension and/or other legal action. You have the right to appeal any violations listed.

Panda Express (Michigan Union)
Michigan Union
530 S. State St.

SFE 5081 248740 11/17/2022 10:30 am

Ann Arbor, MI 48109

Person In Charge (PIC): Jerry Carlson

Establishment Phone:

INSPECTION TYPE:

Follow Up Critical

Violation Category	Repeat	Violation Description/Remarks/Correction Schedule	Correct By	Corrected
--------------------	--------	---	------------	-----------

Corrected

5-205.15		A PLUMBING SYSTEM shall be: (A) Repaired according to LAW; (P) and (B) Maintained in good repair.	11/07/22	11/17/22
----------	--	---	----------	----------

Item(s):	Plumbing system		11/17/2022
Location:	Cook Line Grease Intercept		11/17/2022
Problem(s):	Not repaired according to law		
Correction(s):	Repair according to law.		

11/7/2022 The plumbing system shall be repaired according to law.

Observed the grease interceptor on the kitchen cook line with a fast leak of dirty grease water coming from on the top of the interceptor around the edges of the lid. The grease spilled down the sides of the interceptor and occupied a large space in the cook line. The leak stopped within a minute of starting and employees addressed the leak immediately. Employees poured a large quantity of Dawn dish soap onto the spill before pushing the grease water into a floor trough drain however, grease should not be put into the building main drain system (see attached photos).

Correct as soon as possible by repairing the plumbing system according to law and cleaning any future grease spills by first absorbing as much grease as possible with absorptive material, sweeping up the absorptive material, and then scrubbing the area with soap and water.

11/17/2022

CORRECTED - Grease interceptor (located along cook line) has been repaired and is no longer leaking. Clog has been removed and gasket has been replaced on the grease interceptor (located along cook line). Adam Alobaidy (DSA Housing Services & Student Life Facilities System Trades and System Management Associate Director) was present during the follow up inspection and stated that grease interceptor may be moving to biweekly preventive maintenance schedule (currently on monthly) after study has been performed.

Closing Comments:

Amy White (Michigan Union Director) and Adam Alobaidy (DSA Housing Services & Student Life Facilities System Trades and System Management Associate Director) was present during the follow up inspection.

Priority issue 5-205.15 has been addressed/corrected. All remaining core items shall be addressed/corrected as soon as possible, which will be reinspected the next routine inspection.

Critical / Non-crit	Repeat	Violation Description/Remarks/Correction Schedule	Correct By	Corrected
------------------------	--------	---	------------	-----------

Person in charge (Name and Title)



Inspected By (Name and Title)



This signature does not imply agreement or disagreement with any violation noted.

Nonda Mihas