

## FOOD ESTABLISHMENT INSPECTION REPORT

Based on an evaluation this day, the items marked below are violations of the Michigan Food Law. Violations cited in this report shall be corrected within the time frames specified below, but within a period not to exceed 10 calendar days for priority or priority foundation items (§8-405.11) or 90 days for core items (§8-406.11). Failure to comply with this notice may result in license suspension and/or other legal action. You have the right to appeal any violations listed.

**Blau Kitchen**  
**Ross School of Business**  
**701 Tappan St.**

**SFE 5081 206427 9/14/2023 12:45 pm**

**ZIP CODE NOT FOUND**

**Person In Charge (PIC): Dan Meier**

**Establishment Phone: 734-647-4996**

**INSPECTION TYPE:**

Follow Up Critical

Violation Category	Repeat	Violation Description/Remarks/Correction Schedule	Correct By	Corrected
--------------------	--------	---	------------	-----------

**UnCorrected**

5-205.15		A PLUMBING SYSTEM shall be: (A) Repaired according to LAW; (P) and (B) Maintained in good repair.		09/07/23
----------	--	---	--	----------

**Item(s):** Plumbing system water line(s) hot  
**Location:** hand wash sink(s)  
**Problem(s):** Not maintained  
**Correction(s):** Maintain in good repair

9/7/2023 A plumbing system shall be maintained in good repair.

When attempting to run the hot and cold water faucets at a hand sink in the pantry area of the kitchen, when the hot water handle was turned, no hot water came out of the faucet spout. Cold water ran as expected when the cold water handle was rotated to the 'open' position. Looking under the bowl of the hand sink at the hot and cold water lines from the wall to the faucet, the hot water side shut-off valve was observed completely closed. Opening the hot water shut-off resulted in hot water coming out the spout at the sink when the hot water handle was rotated to the 'open' position, but when attempting to shut off the hot water with the hot water handle, hot water continues to run out of the spout with the hot water handle in the 'closed' position. This explains why the hot water shut-off valve was found completely closed under the sink bowl. Place a work order to have a plumber repair the hot water handle at the hand sink so that the hot water shuts off completely when the hot water handle is in the 'closed' position.

9/14/2023 Hand washing sink still does not have hot water. PIC has placed another work order and will notify me once work order has been completed for additional follow up.

**Closing Comments:**

Additional follow up needed to address/reinspect priority item 5-205.15.

Critical / Non-crit	Repeat	Violation Description/Remarks/Correction Schedule	Correct By	Corrected
------------------------	--------	---	------------	-----------

Person in charge (Name and Title)



This signature does not imply agreement or disagreement with any violation noted.

Inspected By (Name and Title)



Nonda Mihos