

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Dennison Building	Cove Base – Black	170, 182, 269
	Canvas Duct Insulation	1100M
	HVAC Canvas Wrap (Presumed)	BC01, 22, 43, 44J, 56, 70, 78, 80, 84, 176, 284J, 1100M
	Fire Doors (Presumed)	Throughout Building
	Fire Proofing	22, 176
	Floor Tile	221
	Floor Sheeting	Throughout Building
	Lab Sink – Black (Presumed)	1015
	Pipe Insulation (Straights)	2V01, 7V01, 8V01
	Pipe Insulation (Fittings)	Throughout Building
	Pipe Hanger Insulation	9C01, 10C01, 10L01
	Sink Undercoating	919A

*Room numbers listed are as identified at the time of the survey