

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Engineering Research Building II	Canvas HVAC Fabric	247, 1203J, 1231, 1249J, 1F29
	Floor Tile	1202, 1218, 1218A, 1218B, 1230, 1239, 1248, 1251, 1259, 1260
	Fire Doors (Presumed)	Throughout Building
	Fume Hood Liner (Presumed)	214, 1204, 1212, 1218, 1224, 1225, 1230, 1232, 1236, 1240, 1248, 1255, 1264
	Grey Cabinet Liner	214, 1204, 1218
	Lab Drying Rack	1204, 1212, 1224, 1225, 1230, 1232, 1248, 1255, 1256, 1258, 1260, 1264
	Lab Table Top	1204, 1218B, 1224, 1224B, 1230, 1232, 1239, 1248, 1251, 1256, 1256B, 1258, 1260, 1264, 1264B
	Oven Insulation (Presumed)	1232, 1240, 1248A
	Pipe Insulation (Fittings)	Throughout Building
	Sink Undercoating	225, 225A, 248, 260, 1212, 1259, 1260A
	Tank Insulation	215, 247, 1231
	Vinyl Sheet and Backing Material	1218, 1218A, 1218B, IE21

*Room numbers listed are as identified at the time of the survey