

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

Building Name	Material Description	Location*
<b>Molecular &amp; Behavioral Neuroscience Institute</b>	Bay Door Frame Caulk	Building Exterior
	Black Flooring Material	3000
	Black Slate Windowsill (Presumed)	Throughout First & Second Floors
	Cabinet Liner	G042
	Duct Adhesive	G016
	Duct Insulation	G051
	Fire Door (Presumed)	Throughout Building
	Floor Covering & Mastic	Throughout Building
	Flooring Material - Black	3000
	Fume Hood Liner (Presumed)	Throughout Building
	Lab Bench Top (Presumed)	G006, G019, G020, G022, G026, G061C
	Lab Drying Rack (Presumed)	G019, G019A, G028, G042, G050, G059, G061, 2V03, 2023, 2024, 2028, 2040, 2050
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Transite Paneling	Building Exterior
	Wall Caulk	Building Exterior
	Wall Panels	1013, 1055, 1068, 1068A
Window Caulk & Glaze	Building Exterior	

\*Room numbers listed are as identified at the time of the survey