

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
School of Education	Duct Insulation	1214C
	Ceiling Insulation	516, 1211
	Ceiling Panel	1331
	Cove Base	BS31, 1418A
	Fire Door (Presumed)	Throughout Building
	Floor Tile	Throughout Building
	Floor Tile Mastic	1056, 1058, 2S07, 2S08, 2010, 2012, 2014M, 2018M, 2022M, 2026M, 2030M, 2034M, 2038T, 2040, 2040M, 2050M, 2102A
	Light Heat Shield	1309
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Transite Panel	2003D
	Vinyl Floor Sheet & Stair Tread	2S07, 2S08
	Wall Panel Adhesive	2232A

*Room numbers listed are as identified at the time of the survey