

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Vera Baits I – Smith House	Ceiling Tile Gluepods	Throughout Building
	Fire Door (Presumed)	Throughout Building
	Floor Tile	Throughout Building
	Floor Tile Mastic	Throughout Building
	Sink Undercoating	1101
	Stairtread	1S10, 1S20, 1S30, 2S20, 2S30, 3S20, 3S30, 4S10, 4S20, 4S30

*Room numbers listed are as identified at the time of the survey