

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
Biological Station / Stockard Lakeside Laboratory	Fire Doors (Presumed)	1044, 2039, Stairwell 1
	Floor Tile	1043, 2004, 2006, 2045, 1050 Hall, 2000 Hall, 2030 Hall, 2040 Hall, 3027, 3000 Hall, 3030 Hall, Stairwells 1 & 2
	Fume Hood Liner	1047, 1051, 2051, 2053
	HVAC Vibration Dampener	2043
	Lab Drying Racks	Throughout Building
	Lab Bench Tops	Throughout Building
	Light Heat Shields (Presumed)	1035T, 1049, 2027J, 2045, 3027, 3029J, 3031T
	Pipe Insulation (Fittings)	Throughout Building

*Room numbers listed are as identified at the time of the survey