

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

Building Name	Material Description	Location*
<b>C.C. Little Science Building</b>	Cabinet Liner	2566, 4549
	Fire Doors (Presumed)	Throughout Building
	Floor Tile	1C01, 1C11, 1018, 1552, 1558, 2005, 2005A, 2005B, 2007, 2008, 2012, 2502, 2510, 2512, 2516, 2516A, 2540, 2C02, 2C11, 3023, 3024, 3026, 3C02, 3C11, 4015, 4C02, 4C11, 5501
	Fume Hood Liner	2566
	Lab Glove	1608
	Laboratory Drying Rack	Throughout Building
	Pipe Insulation (Straights)	Throughout Building
	Pipe Insulation (Fittings)	Throughout Building
	Vermiculite	1608
	Vinyl Floor Sheet & Mastic	4549
	Window Glaze	1F01, 1S04, 4C01, 5010, 5013, 5014, 5018, 5558A

\*Room numbers listed are as identified at the time of the survey