

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / [OSEHAsbestos@umich.edu](mailto:OSEHAsbestos@umich.edu) or you may refer to the Asbestos Management Program Guideline found on the OSEH website ([www.oseh.umich.edu](http://www.oseh.umich.edu)).

Building Name	Material Description	Location*
<b>Coliseum</b>	Door Frame Caulk	Throughout Building
	Electrical Wire Insulation (Presumed)	Basement
	Floor Tile	1C01, 1C02, 1C03, 1F01, 110, 113, 118, 118A, 126M, 128,
	Floor Tile Mastic	128A, 133, 133C, 133D, 146, 1C01, 1C02, 1C03, 1F01, 110,
	Fire Doors (Presumed)	111, 118, 118A, 113, 131, 131A, 133B, 133C, 133D, 140, 146
	Fire Door Frame (Presumed)	112A, 118, 141M, 141E,
	Galbestos Paneling	112, 112A, 141M, 141E, 152, 160
	Pipe Insulation (Straights)	150, 160
	Pipe Insulation (Fittings)	Basement, 1C01, 200
	Window Frame Caulk	Basement, 1C01, 113A, 140, 200
		110, 111, 113, 113A, 131, 131A, 133, 133B, 133C, 160, 1C01, 200

\*Room numbers listed are as identified at the time of the survey