

The below table describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in in-accessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Occupational Safety & Environmental Health Department (OSEH) at 734-647-1142 / OSEHAsbestos@umich.edu or you may refer to the Asbestos Management Program Guideline found on the OSEH website (www.oseh.umich.edu).

Building Name	Material Description	Location*
G.G. Brown Laboratory	Door Caulk	1022, 1022A, 1504A, 1504B, 2154E, 2152T
	Fire Door (Presumed)	Throughout Building
	Fire Door Frames (Presumed)	Throughout Building
	Floor Tile	Throughout Building
	Lab Bench Top	1164, 1170,1172, 1174, 1180, 2008
	Pipe Insulation (Straights)	1009, 1017, 1029, 1065, 1065A, 1200C, 1200G, 2200A, 2200G, 2170, 2170A, 3000, 3094
	Pipe Insulation (Fittings)	Throughout Building
	Transite Cabinet Liner	1172, 1174, 1176, 1180, 2009, 2178, 2506, 2514, 3335, 3344, 3458
	Transite Door	3016, 3018
	Transite Drying Rack	1164, 3327,3331, 3344, 3458
	Transite Fume Hood	Various Locations Throughout
	Transite Wall	3000, 3016, 3018

*Room numbers listed are as identified at the time of the survey