

The table below describes locations of known or presumed asbestos containing building materials. The table is intended to provide general awareness information to the University community to avoid accidental disturbance of asbestos containing materials. This document should not be relied upon for maintenance, renovation or demolition activities. Additional asbestos containing materials may exist in inaccessible locations, such as above fixed ceilings and inside wall cavities. If you have any questions or concerns regarding asbestos containing materials please contact the Environment Health & Safety (EHS) office at 734-647-1143 or you may refer to the [Asbestos information page](http://www.ehs.umich.edu) found on the EHS website ([www.ehs.umich.edu](http://www.ehs.umich.edu)).

Building Name	Material Description	Location*
<b>Victor Vaughan</b>	Ceiling Tile Glue Pods	Throughout Building
	Pipe Insulation	Throughout Building
	9"x 9" Floor Tile	Throughout Building
	Duct Insulation	Throughout Building
	Door Caulk	Exterior Doors and Interior Doors - 5S, 157, 1C02, GS05, 1S05, 2S05, 3S05
	Stone Panel Caulk	Exterior
	Light Heat Shield	Throughout Building
	Stair Tread	1S02
	Fire Doors (presumed)	Throughout Building

\*Room numbers listed are as identified at the time of the survey